



## INSPECTIONS ROUTE ORDER (Group by: Assigned Inspectors)

Route Order 1 = 8am - 11am

Route Order 2 = 10am- 2pm

Route Order 3 = 1pm - 4pm

## Alan

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
<a href="#">PMT2022-02732</a>	Drywall, Nailing, Interior Lath	1	11/19/2024
<a href="#">PMT2024-02412</a>	Foundation, Footing, Setback	1	11/19/2024
<a href="#">PMT2024-04576</a>	Final Inspection	1	11/19/2024
<a href="#">PMT2024-04105</a>	Electrical Utility Clearance (Edison)	2	11/19/2024
<a href="#">PMT2024-00386</a>	Fire Dampers	2	11/19/2024
<a href="#">PMT2024-04015</a>	Electrical Utility Clearance (Edison)	2	11/19/2024
<a href="#">PMT2024-04015</a>	Final Inspection	2	11/19/2024
<a href="#">PMT2024-04262</a>	Top Out	3	11/19/2024
<a href="#">PMT2024-00946</a>	Electrical Utility Clearance (Edison)	3	11/19/2024
<a href="#">PMT2024-00946</a>	Gas Test	3	11/19/2024
<a href="#">PMT2023-06253</a>	Combination	3	11/19/2024
<a href="#">PMT2023-06253</a>	Exterior Lath	3	11/19/2024
<a href="#">PMT2024-04320</a>	Roof Sheathing, Nailing	3	11/19/2024

## Sebastian

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
<a href="#">PMT2024-00694</a>	Final Inspection	1	11/19/2024
<a href="#">PMT2024-04490</a>	Final Inspection	1	11/19/2024
<a href="#">PMT2024-03504</a>	Rough Electrical	1	11/19/2024
<a href="#">PMT2024-04545</a>	Electrical Utility Clearance (Edison)	1	11/19/2024
<a href="#">PMT2024-04545</a>	Rough - Pre-Final	1	11/19/2024
<a href="#">PMT2024-04056</a>	Electrical Utility Clearance (Edison)	1	11/19/2024
<a href="#">PMT2024-01504</a>	Masonry Steel, Rebar, Grout	2	11/19/2024
<a href="#">PMT2024-04372</a>	Roof Sheathing, Nailing	2	11/19/2024
<a href="#">PMT2024-01953</a>	Final Inspection	2	11/19/2024
<a href="#">PMT2024-00953</a>	Shower / Tub Pan	2	11/19/2024
<a href="#">PMT2024-04601</a>	Final Inspection	2	11/19/2024

## William

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
<a href="#">PMT2024-04497</a>	Roof Sheathing, Nailing	1	11/19/2024
<a href="#">PMT2024-00597</a>	Electrical Utility Clearance (Edison)	1	11/19/2024
<a href="#">PMT2024-00597</a>	Final Inspection	1	11/19/2024
<a href="#">PMT2024-03024</a>	Final Inspection	1	11/19/2024
<a href="#">PMT2024-02311</a>	Pre-Inspection	1	11/19/2024
<a href="#">PMT2024-00332</a>	Final Inspection	1	11/19/2024
<a href="#">PMT2024-01709</a>	Drywall, Nailing, Interior Lath	2	11/19/2024
<a href="#">PMT2024-03628</a>	Drywall, Nailing, Interior Lath	2	11/19/2024
<a href="#">PMT2024-03628</a>	Exterior Lath	2	11/19/2024
<a href="#">PMT2024-01619</a>	Underground Conduit	2	11/19/2024
<a href="#">PMT2024-01620</a>	Underground Conduit	2	11/19/2024
<a href="#">PMT2024-01621</a>	Underground Conduit	2	11/19/2024
<a href="#">PMT2024-01622</a>	Underground Conduit	2	11/19/2024
<a href="#">PMT2024-01623</a>	Underground Conduit	2	11/19/2024
<a href="#">PMT2024-01624</a>	Underground Conduit	2	11/19/2024
<a href="#">PMT2024-01625</a>	Underground Conduit	2	11/19/2024
<a href="#">PMT2024-01626</a>	Underground Conduit	2	11/19/2024
<a href="#">PMT2024-01627</a>	Underground Conduit	2	11/19/2024
<a href="#">PMT2024-01628</a>	Underground Conduit	2	11/19/2024